

## 6.3 x 22mm

### 7AG

"Australux"

32 / 125VAC  
fast, glass



Fast acting for general applications. Also known as '2AG' outside the USA.

PART NO.	AMP	VOLTAGE	PART NO.	AMP	VOLTAGE
7AG-100MA	100mA	125V	7AG-7.5A	7.5A	32V
7AG-250MA	250mA	125V	7AG-10A	10A	32V
7AG-500MA	500mA	125V	7AG-15A	15A	32V
7AG-1A	1A	125V	7AG-20A	20A	32V
7AG-1.5A	1.5A	125V	7AG-25A	25A	32V
7AG-2A	2A	125V	7AG-30A	30A	32V
7AG-3A	3A	125V	7AG-35A	35A	32V
7AG-5A	5A	125V			

## 6.3 x 25.4mm

### 8AG

"Australux"

125 / 250VAC  
fast, glass




Fast acting for general applications

PART NO.	AMP	VOLTAGE	PART NO.	AMP	VOLTAGE
8AG-100MA	100mA	250V	8AG-7.5A	7.5A	125V
8AG-250MA	250mA	250V	8AG-8A	8A	125V
8AG-500MA	500mA	250V	8AG-10A	10A	125V
8AG-1A	1A	250V	8AG-15A	15A	125V
8AG-1.5A	1.5A	250V	8AG-20A	20A	125V
8AG-2A	2A	250V	8AG-25A	25A	125V
8AG-3A	3A	250V	8AG-30A	30A	125V
8AG-4A	4A	250V	8AG-35A	35A	125V
8AG-5A	5A	250V			

### PL

LAWSON FUSES

240VAC  
fast, ceramic



Fast acting for general applications. Known as 'Plug Fuse' for protection applications in the UK. BS1362 approval.

PART NO.	AMP	PART NO.	AMP
PL-1A	1A	PL-7A	7A
PL-2A	2A	PL-10A	10A
PL-3A	3A	PL-13A	13A
PL-5A	5A		

### TDC600

Bussmann

600VAC  
fast, ceramic



Fast acting for general applications. BS1362 approval.

PART NO.	AMP
TDC600-2A	2A
TDC600-10A	10A